

August 2024

Changes in SP8600 Firmware

Dear SP8600 users,

The SP8600 firmware has been updated to fix minor bugs related to printing issues in the "Location Marking" mode and "Mode 3 Marking" mode.

You can download the revised firmware from our website and update the firmware using the PCMS software.

1. Problems Fixed

- ① While in "Location Marking" mode, the drive motor may fail to operate correctly, resulting in a narrower pitch between terminals.
- ② While in "Location Marking" mode, printing defects may occur in the location name.
- ③ While in "Mode 3 Marking" mode, key input may become unresponsive in the middle of marking.

2. How to Download the Firmware and Fix the Bugs

Download the revised firmware from our website and update the firmware of the SP printer using CTKPCMS.

3. Version of the Updated Firmware

Ver.1.00.35e

Sincerely,

CTK Corporation